WING FRAMEWORK

(RIGHT SIDE SHOWN)

NB: DRILL 1/2"⌀ HOLES TO MATCH PLACEMENT OF WING
BRACKETS. DRILL HOLES IN WING BRACKETS WITH
WING IN PLACE TO ENSURE PERFECT MATCH.
DO THIS BEFORE PUTTING THE PLYWOOD ON SO IT IS
LIGHTER TO HANDLE.

✳

NB: WING SUPPORT SHOULD BE 84" LONG — EITHER 2"x1" HSS
OR 2"x2"x1/4" ∠.

BUILD PERIMETER OF WING FRAME FIRST. THEN CUT
INTERIOR ANGLE IRON TO CORRECT LENGTH & ANGLE.

WING FRAME WORK MADE OF
2"x2"x3/16".

1 – LEFT HAND REQ'D
1 – RIGHT HAND REQ'D
– 1/2" PLYWOOD COVER.
– SECURE WITH 1/4"⌀ BOLTS (FLAT HEAD)
OR 10 – 24 x 1 1/2" WAFER HEAD
TEK SCREWS.

DRILL 1/2"⌀ HOLE IN VERTICAL
LEG OF ANGLE TO SECURE WING
SUPPORT INTO POSITIION.

19'–9"±

2'–8"+/–

4'–5"+/–

6'–3"+/–

12"

8'–11"

26'–0"

4'–0" O.C.

4'–0"

8'–0"

EDGE
VIEW